

**Photo 1.** *Site 1.* Historic meander in right overbank (photo is looking upstream)



**Photo 2.** *Site 2.* Historic meander





**Photo 3.** *Site 3.* Over-widened stream reach



**Photo 4.** *Site 4.* Unvegetated overbanks contributing to stream





**Photo 5.** *Site 5.* Minor to moderate erosion on steep bank



**Photo 6.** *Site 6.* Erosion around bridge abutments





**Photo 7.** *Site 8.* Erosion around bridge abutments



**Photo 8.** *Site 9.* Erosion around bridge abutments





**Photo 9.** *Site 10.* Incised stream bed



**Photo 10.** *Site 11.* Minor to moderate erosion on outside of bank meander





**Photo 11.** *Site 12.* Minor to moderate erosion on stream bank



**Photo 12.** *Site 13.* Minor to moderate erosion on outside of bank meander





**Photo 13.** *Site 14.* Eroded culvert outfall



**Photo 14.** *Site 15.* Minor to moderate erosion on outside of stream bend





**Photo 15.** *Site 16.* Significant erosion on outside of stream bend



**Photo 16.** *Site 17.* Minor to moderate erosion on outside of stream bend





**Photo 17.** *Site 18.* Large woody debris in stream



**Photo 18.** *Site 19.* Large woody debris in stream





**Photo 19.** *Site 20.* Meander in process of being cut off



**Photo 20.** *Site 21.* Over-widened stream reach

